




- 1 Connection to existing sidewalk
- 2 Mid-block pedestrian crossing with flashing light
- 3 Future Maintenance Building
- 4 North Maintenance Annex
- 5 Maintenance parking lot
- 6 Vehicle turnout
- 7 Connection to existing trail
- 8 Vegetative screening
- 9 Rain garden with interpretive sign
- 10 Landscape boulders
- 11 Existing driveway to remain



SCHEMATIC PLAN

Si View Park Trail Connection, North Bend, Washington